

## **HISC<sup>™</sup> High Intensity Separation Conveyor<sup>™</sup>**

### **ASR Stainless Steel Separation & Zurik Purification**

Bunting® Magnetics Co. offers the strongest HISC<sup>™</sup> High Intensity Separation Conveyor<sup>™</sup> in the ASR (Auto Shredder Residue) Industry for the separation of work hardened stainless steels and the purification of Zurik fraction and fluff applications. Maximum ferrous and work-hardened stainless steel – materials once thought impossible to separate – are easily removed thanks to extremely high gauss fields, neodymium rare earth magnets and innovative design technology.



### Features

- 2 Standard HISC<sup>™</sup> Pulley diameters in 4" and 6" diameters with extremely high gauss fields for separation of paramagnetic and work-hardened stainless steel.
- Stainless Frame discharge ends for extremely strong magnetic fields.
- Heavy duty formed 3/16" frames with forklift lifting slots through the frame.
- Heavy duty formed 3/16" sideguards over the flexwall belt to seal off and contain the flow.
- Standard tough urethane to match the application for maximum effectiveness.
- Optional lengths for the addition of Overhead Magnetic Crossbelts towards in feed.
- Optional Variable Frequency Drive to optimize separation for belt speeds between 60 and 200 fpm.
- Optional Vibratory Feeders to spread material to single layer for max separation effectiveness.
- Optional support stands and/or machine bases to tie into your system.

500 S. Spencer Rd. Newton, Kansas 67114 800-835-2526 or 316-284-2020 Fax: 316-283-4975 Email: bmc@buntingmagnetics.com www.buntingmagnetics.com



# **BUNTING** Magnetics Co.

## Holding – Attracting – Extracting High Intensity Separation Convert

Bunting Engineers, using world-class Magnetic Finite Element design technology, and extremely strong Neodymium Rare Earth magnetic circuity have made the HISC<sup>™</sup> High Intensity Separation Conveyor<sup>™</sup> the best choice for recyclers. Optimized gauss levels on the surface of the pulley and the belt hold, attract and extract your stainless steel alloys. These forces can vary depending on the alloy or the degree of work-hardening done.

Since material alloy, size, shape and gauge can all affect the attractive force, we can test and video your material fraction to make recommendations.



Note: Generally 2" minus fractions work great on 4"diameter HISC<sup>™</sup> Pulleys while larger 4"minus fractions need the 6" diameter HISC<sup>™</sup> Pulleys.

### **Typical Industrial Applications**

- Auto ASR Stainless Steel Separation
- Zurik Stainless Steel Purification
- Plastic Flake Purification
- Medical Waste Separation
- Electronic Recycling

### **HISC Model Number Selection Guide**

Pulley Diameter	Belt Width	Conv Length	Model Number
4"	12"	36"	HISC 4-12-36
4"	18"	36"	HISC 4-18-36
4"	24"	72"	HISC 4-24-72
4"	36"	72"	HISC 4-36-72
4"	48"	96"	HISC 4-48-72
6"	18"	36"	HISC 6-16-36
6"	24"	72"	HISC 6-24-72
6"	36"	72"	HISC 6-36-72
6"	48"	96"	HISC 6-48-96
6"	60"	120"	HISC 6-60-120



Scan QR Code to watch a video

General Capacities are between 500 to 1,000#/hr per foot width of conveyor.

For More Information and Technical Assistance: 800-835-2526 • www.buntingmagnetics.com • bmc@buntingmagnetics.com

HISC<sup>™</sup> and High Intensity Separation Conveyor<sup>™</sup> are registered trademarks of Bunting<sub>®</sub> Magnetics Co.